


Reading Your Report

The purpose of the report is to help a prospective buyer make an informed decision about the house they are interested in. The report will document the current condition, and identify any impending repairs, based on a visual inspection of the home.

How the report works

This report provides a comprehensive package which simplifies buying and owning a home. The report can identify things at a glance, or provide in-depth explanations. It can identify maintenance items and can even act as a work order for contractor repairs.



Easy to navigate and find information.

Tabs for each home system are labeled and color coded at the top of the report pages, clicking on any tab will take you directly to that system or scroll through page by page.

Easy to read and understand.

This report is organized in 3 layers

1. Provide the **BIG** picture!

An executive summary addressing significant issues to help you make a purchasing decision. You should read the full report to get the whole picture.

2. Once you've moved in!

Outline of major and minor issues, where appropriate helping to protect your investment.

3. When you need the precise details!

Color illustrations and links to reference articles helping you understand all of the components of your house.

Added benefits:

- Electronic .PDF file report is secure and universally readable on any computer (free Adobe reader available online). Print if you want.
- Clear, colorful illustrations to exemplify conditions.
- Articles that explain technical issues in plain words.
- It's Green! Environmentally friendly, ink and paper free report.

Report features

- You will receive an email with your Inspection Report Link. Click to open.
- Save your report to your computer or CDrom. View anytime using Adobe reader.
- Print or email the report as needed.

Print or Save a copy of your report to your computer.

Click any of the Color coded tabs to navigate to a section of the report.

'Click' on Hyperlinks to open technical articles for detailed information.

Adobe Reader - [FullReport.pdf]

File Edit View Document Tools Window Help

27 Maple Crescent, Chicago, IL January 4, 2007 Report No. 1366, v.6
www.xyzhomeservices.com

SUMMARY ROOFING EXTERIOR **STRUCTURE** ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

DESCRIPTION

Configuration: • [Basement](#) • [Crawl space](#)

Foundation material: • [Poured concrete](#)

Floor construction: • [Joists](#)

Exterior wall construction: • [Wood frame](#) • [Wood frame, brick veneer](#)

Roof and ceiling framing: • [Trusses](#)

LIMITATIONS

Inspection limited/prevented by: • The attic/roof space was inspected from the access hatch. All areas could not be closely examined. • Some parts of the foundation walls were not visible and could not be inspected.

Inspection limited/prevented by: • Carpet/furnishings • Storage

RECOMMENDATIONS

Floors > Joists

Condition: • [Notches or holes](#)

Implication(s): Weakened structure

Location: West Basement

Task: Repair

Time: Immediate

Joist notching and drilling

notches in top or bottom of joist to be maximum 1/5 joist depth and are not allowed in the middle third of the span (USA)

joist notching only allowed at the top of the ends of the joists in Canada

effective joist depth

2" min

2" min

maximum hole diameter: 1/3 joist depth (USA) 1/4 joist depth (CAN)

maximum notch depth at end of joist: 1/4 joist depth (USA) 1/3 joist depth (CAN)

maximum 1/2 joist width (CAN)

Click on image to enlarge.

At XYZ Home Inspections, a great inspection is only the beginning. Page 8 of 30

Full color illustrations. Click to enlarge image.

Navigate page by page.